03500.017564 <u>PATENT</u>

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:)	Examiner: Eugene Lee
MOTOKAZU KOBAYASHI ET AL.		;	Group Art Unit: 2815
Appln. No.: 10/662,472		;	U.S. Patent No.: 7,187,024 B2
Filed: September 16, 2003		:	Issued: March 6, 2007
For:	PIEZOELECTRIC ELEMENT, INK JET RECORDING HEAD AND METHOD FOR MANUFACTURING PIEZOELECTRIC	;) ;	Confirmation No.: 9615
	ELEMENT	:	March 11, 2008

Commissioner for Patents P.O. Box 1450 Alexandria, Virginia 22313-1450

CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (PTO-1050) is attached.

The \$100.00 fee for this Certificate of Correction is being paid electronically.

The Commissioner is authorized to charge any underpayment, or credit any overpayment, to

Deposit Account No. 06-1205.

Patentees' undersigned attorney may be reached in our Washington, D.C.

office by telephone at (202) 530-1010. All correspondence should continue to be directed to our

address given below.

Respectfully submitted,

/Lawrence A. Stahl/

Lawrence A. Stahl Attorney for Patentees Registration No. 30,110

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza New York, New York 10112-3800

Facsimile: (212) 218-2200

LAS:eyw

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. : US 7,187,024 B2

DATED : March 6, 2007

INVENTOR(S): MOTOKAZU KOBAYASHI ET AL. Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 24, "on" should read --in--.

COLUMN 2

Line 14, "certain" should read --with certain--.

Line 20, "out of align-" should read --misalign- --.

Line 58, "has" should read --have--.

COLUMN 4

Line 39, "M₁RuO₃" should read --M¹RuO₃--.

Line 58, "acitnitrile." should read --acetonitrile.--.

COLUMN 6

Line 17, "is" (second occurrence) should read --be--.

Line 48, "make the electrode to" should read --give the electrode--.

COLUMN 7

Line 5, "disappear" should read --erase--.

Line 27, "disappear" should read --erase--.

COLUMN 8

Line 64, "the" (first occurrence) should be deleted.

Line 65, "by" should be deleted.

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 7,187,024 B2</u>

No. of add'l. copies @ 30¢ per page

30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone

FITZPATRICK, CELLA, HARPER & SCINTO

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

FCHS_WS 1649764 v1

□> _____

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. : US 7,187,024 B2

DATED : March 6, 2007

INVENTOR(S): MOTOKAZU KOBAYASHI ET AL. Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 9

Line 24, "by" should be deleted. Line 46, "by" should be deleted.

COLUMN 10

Line 2, "by" should be deleted.

Line 37, "by" should be deleted.

Line 57, "by" should be deleted.

COLUMN 11

Line 42, "alternative" should read --alternating--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. <u>US 7,187,024 B2</u>

No. of add'l. copies @ 30¢ per page

